

AMIKON TECHNICAL DOCUMENTATION

Installation Instructions

ICS Triplex T8292C

Trusted MCB power distributor

BRANCHES	INPUT LIMIT	PROTECTION	ALARM
4 dual + auxiliary	60 A maximum	MCB branches	Volt-free contact

For qualified personnel only. This installation summary is not a substitute for the controlled manufacturer procedure, system safety plan or approved site isolation requirements.

01

BEFORE INSTALLATION

Identity and revision	Verify the complete T8292C label, revision and installation location.
Voltage applicability	Resolve RM261 versus PC002G voltage limits for the supplied hardware.
Feeder and link arrangement	Match the approved N+1 or separated redundant feeder design.
Branch and cable selection	Verify branch ratings, approved cable assemblies and total loading.
Mounting and alarm	Check DIN rail support, alarm wiring and access to breaker indicators.

02

PREPARATION AND BOUNDARIES

- Qualified personnel must follow the approved isolation, electrical safety and ESD procedures. The current catalogue lists ordinary-location scope; do not infer hazardous-area suitability from general manual warnings.
- RM261 Issue 10 gives 22-28 Vdc, whereas PC002G gives 18-28 Vdc. Confirm the actual revision rating. Read the complete feeder diagrams and terminal tables before any connection or link change.

03
INSTALLATION AND COMMISSIONING

01	Record full identity, revision, approved site location, voltage scope and the intended redundancy design.
02	Isolate both affected feeders and downstream circuits under the controlled maintenance procedure.
03	Mount on the specified DIN rail, inspect terminals and preserve safe access to the breakers and indicators.
04	Check the N+1 link and feeder allocation. Independent supplies must follow the documented cross-feeder arrangement, not two terminals from one feeder.
05	Verify branch ratings, total input load, cable selection and the common alarm circuit against the original drawings.
06	Restore service under the commissioning plan. Verify feeder-health indication, branch status and alarm response before release.

04
SAFETY AND FINAL CHECKS

- A red indicator identifies an associated tripped breaker; the common alarm contact opens on trip. Investigate the circuit under the approved maintenance procedure rather than repeatedly resetting the breaker.
- For units through issue 5, the manual limits the difference between supply feeds to 1 V. Verify the actual issue and controlled instructions; do not assume a later revision from the C suffix.

05
OFFICIAL PROCEDURE

PD-T8292 Issue 10 | Power Distribution Unit MCB 24 Vdc

PDF pp. 1, 12-15: purpose and feeder paths; pp. 17-21: configuration and mounting; pp. 23, 25-26: cables, terminals and ratings.

PC002G - voltage, location and C-suffix scope, PDF pp. 4 and 6

Independent Amikon reference, not an OEM manual. Use the complete manufacturer instructions matching the actual hardware and firmware. No manufacturer pages are reproduced.

AMIKON PRODUCT SUPPORT

+86-18020776786

INFO@AMIKON.CN

AMIKONG.COM


06

ORIGINAL REFERENCE SCHEMATICS

ICS Triplex T8292C | Documented installation context

Original Amikon illustration based on the linked OEM pages. Logical arrangement only; not to scale and not an electrical wiring or manufacturer installation drawing.

A | EQUIPMENT ARRANGEMENT



The factory N+1 link joins the arrangement described by the manufacturer. Separated redundant operation requires the documented link state and feeder allocation.

TB1 and TB2 draw from feeder 1; TB3 and TB4 draw from feeder 2. This logical summary is not a connector pinout or an instruction to rewire live equipment.

B | CONFIGURATION BOUNDARY

Match T8292C and the actual revision, voltage applicability, link position, feeder allocation and load schedule. PC002G lists ordinary-location scope for this family. Do not infer hazardous-location suitability or an automatic redundant connection from the product name.

07

ORIGINAL MANUFACTURER DRAWING AND PROCEDURE LINKS

- Original breaker and alarm schematic - PDF page 12
- Single-line feeder allocation - PDF page 13
- Complete terminal connection table - PDF page 25

If the viewer ignores the page target, enter the stated PDF page manually. Retain the full manufacturer warnings and approved maintenance plan; this reference does not authorize live work.