

AMIKON TECHNICAL DOCUMENTATION

Installation Instructions

ICS Triplex T7310

Regent Plus I/O transceiver module

PLATFORM	CHASSIS QTY	INTERFACE	DISSIPATION
Regent Plus	3 transceivers	I/O Safetybus	8 W

For qualified personnel only. This installation summary is not a substitute for the controlled manufacturer procedure, system safety plan or approved site isolation requirements.

01 BEFORE INSTALLATION

Exact identity	Confirm T7310 and the Regent Plus platform against the installed module label.
Chassis position	Three T7310 transceivers occupy the three leftmost positions of each I/O chassis.
Power and interface	Retain the assigned processor, I/O Safetybus leg and corresponding I/O power supply connections.
Addressing	Compare the I/O chassis identification switch setting with the approved controller configuration.
Maintenance authority	Use the qualified-personnel Regent Plus procedure for the actual redundant arrangement and process state.

02 PREPARATION AND BOUNDARIES

- Use the full manufacturer and chassis instructions; the supplied reference is not a field wiring or mechanical fitting drawing.
- The manual describes hot replacement within the triplicated arrangement. This does not authorize interruption of healthy redundant legs or bypassing process safeguards.

03
INSTALLATION AND COMMISSIONING

01	Record the complete T7310 identity, I/O chassis address and assigned transceiver position.
02	Confirm the corresponding controller processor and I/O Safetybus leg against approved drawings.
03	Verify the associated I/O power supply and the approved maintenance or isolation conditions.
04	Follow the controlled Regent Plus chassis procedure; do not apply Trusted module ejector or SmartSlot instructions.
05	Check ACTIVE and FAULT indications and the controller I/O module error indication after the approved replacement.
06	Confirm normal addressed I/O communications and complete the required operational checks before release.

04
SAFETY AND FINAL CHECKS

- Processor-initiated loopback tests check transceiver health. A reported failure produces a controller I/O error indication and a transceiver fault indication.
- There are no user-replaceable internal parts. A power-supply failure can shut down its associated transceiver; investigate the complete communication and supply path.

05
OFFICIAL PROCEDURE

ICSTT-RM039 | PD-7009 Issue 1

PDF pp. 1-2: operation; pp. 3-4: diagnostics and front view; pp. 5-6: specifications.

Independent Amikon reference, not an OEM manual. Use the complete manufacturer instructions matching the actual hardware and firmware. No manufacturer pages are reproduced.

AMIKON PRODUCT SUPPORT

+86-18020776786

INFO@AMIKON.CN

AMIKONG.COM

06

ORIGINAL REFERENCE SCHEMATICS

ICS Triplex T7310 | Documented installation context

Original Amikon illustration based on the linked OEM pages. Logical arrangement only; not to scale and not an electrical wiring or manufacturer installation drawing.

A | EQUIPMENT ARRANGEMENT



Three transceivers occupy the three leftmost I/O chassis slots; each serves one processor and one Safetybus leg.

Each transceiver receives power from its corresponding I/O power supply; this logical diagram assigns no electrical terminals.

B | CONFIGURATION BOUNDARY

Verify T7310, the Regent Plus I/O chassis and the matched triplicated communication and power arrangement. Trusted expansion interfaces are not established substitutes.

07

ORIGINAL MANUFACTURER DRAWING AND PROCEDURE LINKS

[Original transceiver block diagram - PDF page 2](#)

[Original module front view - PDF page 4](#)

[Maintenance and specification scope - PDF page 5](#)

If the viewer ignores the page target, enter the stated PDF page manually. Retain the full manufacturer warnings and approved maintenance plan; this reference does not authorize live work.