
3300 XL Extension Cable

330130-AXXX-BXX-CXX

Note: Make sure that the extension cable length and the probe length, when added together, equal the Proximitor® Sensor total length.

Option Descriptions

A: Cable Length Option

- 0 3 0 3.0 metres (9.8 feet)
- 0 3 5 3.5 metres (11.5 feet)
- 0 4 0 4.0 metres (13.1 feet)
- 0 4 5 4.5 metres (14.8 feet)
- 0 7 0 7.0 metres (22.9 feet)
- 0 7 5 7.5 metres (24.6 feet)
- 0 8 0 8.0 metres (26.2 feet)
- 0 8 5 8.5 metres (27.9 feet)

B: Connector Protector and Cable Option

- 0 0 Standard cable
- 0 1 Armored cable
- 0 2 Standard cable with connector protectors
- 0 3 Armored cable with connector protectors
- 1 0 FluidLoc® cable
- 1 1 Armored FluidLoc® cable
- 1 2 FluidLoc® cable with connector protectors
- 1 3 Armored FluidLoc® cable with connector protectors

C: Agency Approval Option

- 0 0 Not required
- 0 5 Multiple Approvals

3300 XL Extended Temperature Range (ETR) Extension Cable

330190-AXXX-BXX-CXX

Note: Make sure that the extension cable length and the probe length, when added together, equal the Proximitor® Sensor total length.

Option Descriptions

A: Cable Length Option

- 0 3 0 3.0 metres (9.8 feet)
- 0 3 5 3.5 metres (11.5 feet)
- 0 4 0 4.0 metres (13.1 feet)

- 0 4 5 4.5 metres (14.8 feet)
- 0 7 0 7.0 metres (22.9 feet)
- 0 7 5 7.5 metres (24.6 feet)
- 0 8 0 8.0 metres (26.2 feet)
- 0 8 5 8.5 metres (27.9 feet)

B: Cable Option

- 0 0 Standard cable
- 0 1 Armored cable

C: Agency Approval Option

- 0 0 Not required
- 0 5 Multiple Approvals

Accessories

141078-01

Manual

159484

Performance Specification – 3300 XL Proximity Transducer System

162735

Performance Specification – 3300 XL ETR probes and extension cables

02120015

Bulk field wire. 1.0 mm² (18 AWG), 3 conductor, twisted, shielded cable with drain wire. Specify length in feet.

137491-AXX

Aluminum probe clamp bracket²

Option Descriptions

A: Mounting screw option

- 0 1 10-24 UNC-2A mounting screws
- 0 2 M5 x 0.8-6g mounting screws

The aluminum clamp bracket is an unthreaded mounting bracket designed to use with the smooth case probes (330140, 330141, 330197 and 330198). After gapping the probe, tighten the clamp bracket by tightening the screws. The mounting screws have pre-drilled holes for safety wire.

137492-AXX

Aluminum probe threaded mounting bracket

Option Descriptions

A: Thread size

- 0 1 3/8-24
- 0 4 M10 x 1

The aluminum probe threaded mounting bracket is the standard mounting bracket for most 3300 and 3300 XL probe