

HONEYWELL

CC-TSP411-51306669-175

Speed Protection IOTA

01

BEFORE INSTALLATION

- Confirm the exact model and current controlled manufacturer documentation.
- Verify the documented power source, enclosure, environmental limits and approval marking.
- Record the installed wiring, settings and associated system components.
- Installation must be performed by qualified personnel.

SAFETY NOTE

Follow Honeywell controlled instructions and all applicable site safety, electrical and hazardous-area procedures.

HONEYWELL

CC-TSP411-51306669-175

Speed Protection IOTA

02

MOUNTING AND CONNECTION

- Use only the documented mounting orientation and hardware.
- Keep the unit protected within the required industrial enclosure.
- Connect only manufacturer-supported field wiring, power and associated modules.
- Preserve grounding, separation and intrinsically safe wiring requirements where applicable.

SAFETY NOTE

Follow Honeywell controlled instructions and all applicable site safety, electrical and hazardous-area procedures.

HONEYWELL

CC-TSP411-51306669-175

Speed Protection IOTA

03

COMMISSIONING AND REPLACEMENT

- Inspect the complete order code before energizing.
- Verify wiring continuity, polarity, terminations and configured settings.
- Confirm status indications and system response before returning equipment to service.
- Do not substitute a related model without documented compatibility review.

04

CONTROLLED INSTALLATION NOTE

Follow Honeywell controlled instructions and all applicable site safety, electrical and hazardous-area procedures.